

Magi No.

DOE \_\_yes \_\_no

# Maryland Historical Trust State Historic Sites Inventory Form

## 1. Name (indicate preferred name)

historic Frame house

and/or common

## 2. Location

street & number north side of Sandy Hook Road, .15 mile west of Clark Road not for publicationcity, town Sandy Hook \_\_\_\_\_ vicinity of \_\_\_\_\_ congressional district sixthstate Maryland county Washington

## 3. Classification

<b>Category</b>	<b>Ownership</b>	<b>Status</b>	<b>Present Use</b>	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

## 4. Owner of Property (give names and mailing addresses of all owners)

name

street &amp; number \_\_\_\_\_ telephone no.: \_\_\_\_\_

city, town \_\_\_\_\_ state and zip code \_\_\_\_\_

## 5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liberstreet & number Washington Street foliocity, town Hagerstown state Maryland

## 6. Representation in Existing Historical Surveys

title

date \_\_\_\_\_ federal \_\_\_\_\_ state \_\_\_\_\_ county \_\_\_\_\_ local \_\_\_\_\_

depository for survey records

city, town \_\_\_\_\_ state \_\_\_\_\_

## 7. Description

Survey No. WA-III-103

### Condition

☐ excellent  
☐ good  
☒ fair

☐ deteriorated  
☐ ruins  
☐ unexposed

### Check one

☐ unaltered  
☒ altered

### Check one

☒ original site  
☐ moved      date of move \_\_\_\_\_

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story gable front structure with a rectangular plan on a high stone foundation. The structure is three-bays by three-bays and has a full-length, one-story front porch. The narrowness of the main facade and the height of the structure due to its high stone foundation give the structure an overall effect that is sharply vertical. The main facade is symmetrically arranged with a central entrance. This structure appears to date from the late 19th century.

The property is located on the north side of Sandy Hook Road, approximately .15 mile west of Clark Road in Sandy Hook. The structure is built into a slight slope in the ground and has a high stone foundation. The main facade faces south.

The two-story structure is constructed of frame covered in an asphalt siding imitating block. The main facade has a gable front with wood ornamentation on the gable and on the full-length, one-story front porch. The front porch has a long set of stairs rising in the center in front of the high stone foundation. The porch is supported by wood posts covered in asphalt siding. The porch has a shed roof, boxed cornice, brackets with ornamental pendants on the outer corners, chamfered posts, and a stick railing. The house has a central entrance with two-over-two sash windows in the outer bays. One-over-one sash windows are in the outer bays of the second story. The house has corner boards and gable ends have ornamentation at the corner. The sides of the house have window sash similar to that found on the main facade. The gable roof is covered in sheet metal.

## 8. Significance

Survey No. WA-III-103

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

### Specific dates

### Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☒ C ☐ D  
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site is a contributing structure in the Sandy Hook  
Survey District.

## 9. Major Bibliographical References

Survey No. WA-III-103

## 10. Geographical Data

**Acreage of nominated property** \_\_\_\_\_

**Quadrangle name** \_\_\_\_\_

**Quadrangle scale** \_\_\_\_\_

**UTM References** do NOT complete UTM references

**A**

Diagram A shows three separate coordinate axes. The first axis is labeled 'Zone' and has two tick marks. The second axis is labeled 'Easting' and has four tick marks. The third axis is labeled 'Northing' and has four tick marks. Each axis is represented by a horizontal line with vertical tick marks extending upwards.

Zone Easting Northing

**B**

Three empty bar charts are shown, each with a horizontal axis and a vertical axis. The first chart is labeled 'Zone' and has 5 tick marks on the horizontal axis. The second chart is labeled 'Easting' and has 10 tick marks on the horizontal axis. The third chart is labeled 'Northing' and has 10 tick marks on the horizontal axis.

Zone Easting Northing

**c**

D

E                                                     

F

**G** 

H 

### Verbal boundary description and justification

**List all states and counties for properties overlapping state or county boundaries**

state	code	county	code
-------	------	--------	------

state	code	county	code
-------	------	--------	------

**11. Form Prepared By**

**name/title** Joe Getty

**organization** Maryland Historical Trust

date April 1983

**street & number** 21 State Circle

**telephone**

city or town Annapolis

state Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust  
Shaw House  
21 State Circle  
Annapolis, Maryland 21401  
(301) 269-2438

# FREDERICK & INGTON

HARPERS FERRY, VA-MD-W VA  
QUADRANGLE

USGS 7.5 minute map  
1:24 000  
1969

COMMONWEALTH OF VIRGINIA  
DIVISION OF MINERAL RESOURCES  
JAMES L. CALVER, STATE GEOLOGIST





1. WA-III-103
2. Washington Co., Md.
3. Joe Getty
4. ~~April 1985~~ 7/82
5. Md. Hist. Trust, Annapolis, Md.
6. South elev. (camera facing north)
7. 1/1